

Picnic Toilets, Golf Course

Herrick Archives Number H 330

A. IDENTIFICATION & LOCATION

1. Name

1.1 Never officially named by Board of Trustees action.


1.2 Alternate names noted:

"Restrooms" on some maps

2. Location

2.1 Located about 350' north of Club House (033). See map below.

See Addendum No. 1



3. General Description

3.1 Type of construction:

Not known. Pictures suggest concrete block or wood walls and sloping wood roof.

3.2 No. of stories:

None

3.3 Increments of construction:

None.

3.4 Size of buildings:

Not known. Preliminary plans sent to John S. McCoy, Superintendent of the Golf Course, by Howard Dwight Smith, University Architect, on May 2, 1941 Bbcwd two buildings, each 6'6"x 15'2". The buildings as constructed did not follow these plans as to roof design and wall materials, but were at least close to the sizes suggested in the preliminary plans.

B. PLANNING, CONSTRUCTION & DEMOLITIONS

1. Records are quite incomplete. The drawing referred to above was dated May 1, 1941 and revised May 2, 1941. Three copies were sent to John S. McCoy on May 2, 1941. The drawing bears the number 4050, which is the project number for the second addition to the Club House (033), which was completed in April, 1941. Presumably the toilets were built shortly thereafter. This presumption, was confirmed by Mr. John S. McCoy in a conversation on December 15, 1975.
2. On January 8, 1947, John S. McCoy (Golf Course Superintendent,) wrote to Athletic Director L. W. St. John recommending big removal of the toilets because they were not used by picnic groups and were hard to keep clean and in repair.
3. The Athletic Board minutes for its meeting on February 19, 1947 show an addition of \$3000 to the budget for removal of these toilets and two other projects.
4. On December 15, 1975 Mr. McCoy confirmed that these toilets were removed soon after the Athletic Board action.

C. PHOTOGRAPHS

1. In Photoarchives:

X22614

John H. Herrick
January 20, 1976

ADDENDUM NO. 1

Address arbitrarily assigned for indexing purposes: Golf Course (interior).

John H. Herrick
February 19, 1976